

FIG 1

FIG 2




FIG. 3

F16.4

FIG. 5 is a cross-sectional view of a mechanical assembly. The assembly includes a central horizontal member (50) with a central opening (92) and side openings (94). This member is flanked by vertical members (30) which have internal features (32, 36, 54). The entire assembly is supported by a base (44) with a central protrusion (46) and side supports (72, 74). Various other components are labeled with numbers like 20, 22, 24, 26, 28, 38, 40, 42, 48, 58, 62, 64, 70, 76, 78, 82, 84. Arrows indicate directions of movement or force.

FIG. 5